Installing Beam

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Vehicle/pedestrian accident	Hard Hat	
Contact with equipment	Steel Toed Boots	
Pinch points	Work Gloves	
Trips/slips	High Vis Vest	
Fall from ladder		

Safe Work Procedure:

- 1) Assist crane truck operator to guide the beam into position
- 2) High Visibility vests must be worn by all workers at all times when the crane is on site.
- 3) When beam is in position workers will entered the interior to the basement to place teleposts into position under the beam
- 4) Secure beam in place to the foundation and teleposts
- 5) Disconnect the crane from the beam

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards:	This Safe Work Procedure will be reviewed any	
	time the task, equipment or materials change	
MB Workplace Safety & Health Act & Regulations:	and at a minimum of every three years	
Part 6 Personal Protective Equipment	Reviewed By WSH Committee:	
Part 20 Vehicular and Pedestrian Traffic		
Part 23 Cranes & Hoists		
	Date:	