## Jumping Jack Inspection

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Eye Injuries	Steel toed boots	
Hand Injuries	Eye protection	
Noise Pollution	Hand protection	
Pinch Points	Hearing protection	
	Hard hat	

## Safe Work Procedure:

- 1) Check On/Off switch is functioning properly.
- 2) Check pull start cord for frays.
- 3) Check air filter.
- 4) Check gas levels.
- 5) Check spark plug.
- 6) Ensure that machine has not been altered in any way before starting.
- 7) Report to supervisor if machine does not meet requirements.

## If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

## REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards: MB Workplace Safety & Health Act & Regulations:	This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years	
4 General Workplace Requirements 5 First Aid	Reviewed By WSH Committee:	
6 Personal Protective Equipment 16 Machines, Tools and Robots 16.15 Miscellaneous Machines and Tools	Date:	