Portable Generator

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Inhalation of carbon monoxide	Steel toed boots	Manufacturer's Manual
Fire/Explosion	Eye protection	
Burns	Hand protection	
Electrocution	Steel toed boots	
Slip/Trip	Hearing Protection	

Safe Work Procedure:

- 1) Pull generator to well ventilated work area.
- 2) Ensure generator is fueled, and inspect it before starting.
- 3) Place cord out of way of workers walk path when possible.
- 4) If work area becomes wet, stop work with generator immediately.
- 5) Ensure machine is turned off and unplugged when not in use.

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards:	This Safe Work Procedure will be reviewed any time the task, equipment or materials change
MB Workplace Safety & Health Act &	and at a minimum of every three years
Regulations:	Reviewed By WSH Committee:
6 Personal Protective Equipment 12.3 Hearing Protection 16.4 Machine and Tool Safety 19.10 Fire and Explosion Hazards	Date: