Shearer - Operation

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:	
Flying debris	Eye protection	Operation and Maintenance	
		Manual	
Overhead lines	Hard Hat		
	Steel Toed Boots		
	Hi Vis Vest		

Safe Work Procedure:

- 1) Make sure all protective guards and covers are in place.
- 2) Only operate machine while you are in the seat with the seat belt on
- 3) Operate the attachment slowly in open area and check for proper operation of controls and protective devices
- 4) Ensure no personnel are in harm's way
- 5) Not any repairs during operation of attachment and report them to your supervisor
- 6) Carry attachments approximately 5inches about ground level.
- 7) Maintain control of the machine when operating the attachment and don not overload the machine beyond its capacity.
- 8) Maintain a line of sight with the attachment at all times

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards:	This Safe Work Procedure will be reviewed any	
	time the task, equipment or materials change	
MB Workplace Safety & Health Act & Regulations:	and at a minimum of every three years	
	Reviewed By WSH Committee:	
Part 22 Powered Equipment General		
	Date:	