

Shearer – Pre-Operation

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

<i>Hazards Present:</i>	<i>PPE or Devices Required:</i>	<i>Additional Training Required:</i>
Personnel	Eye protection	Operation and Machine
Obstacles	Hard Hat	Maintenance Manual
Overhead lines	Foot Protection	
	Hi Vis Vest	

Safe Work Procedure:

- 1) Clear all personnel from the area
- 2) Clear all obstacles that are in the path of the machine
- 3) Beware of overhead lines
- 4) Ensure the use of eye, foot and head protection at all times, and any other equipment that is required on the job site.
- 5) Refer to the Operation and Maintenance Manual, Walk-Around Inspection for information on inspecting the attachment before operation.

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards:	This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years
MB Workplace Safety & Health Act & Regulations:	
Part 22 Powered Mobile Equipment General	Reviewed By WSH Committee:
	Date: