Load Crawling Loader

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Slip/Trip hazard	Steel toed boots	Operator training
Fall injury	Safety glasses	
Vehicle/Machine damage	Hand protection	
Pinch points	Hard hat	

Safe Work Procedure:

- 1) Enter crawling loader using 3 point contact method
- 2) Drive up to back of trailer, making sure you are straight and properly aligned.
- 3) Raise bucket on to deck and use bucket to raise the loader
- 4) Move ahead slowly until front of tracks are on the trailer
- 5) Proceed to the front of the trailer carefully
- 6) Lower bucket and set parking brake
- 7) Exit cab using 3 point contact method
- 8) Dismount trailer by sitting on deck and pushing of. Jumping off trailers is prohibited
- 9) Secure loader with two chains using 4 point contact
- 10) Inspect load and proceed to job

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards:	This Safe Work Procedure will be reviewed any
MB Workplace Safety & Health Act & Regulations:	time the task, equipment or materials change and at a minimum of every three years
4 General Workplace Requirements	Reviewed By WSH Committee:
6 Personal Protective Equipment 16 Machines, Tools and Robots 22 Powered Mobile Equipment	Date: