Move Disabled Vehicles

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Slip/Trip hazard	Steel Toed Boots	
Fall Injury	Safety Glasses	
Vehicle/Machine damage	Hand Protection	
Pinch Points	Hard Hat	

Safe Work Procedure:

- 1) Use a rigid type coupler.
- 2) Put transaxle in neutral and put machine in the transport position and raise loader as required.
- 3) Make sure truck and machine are equipped with correct safety equipment and that there is a block at the front and rear of each trailer wheel.
- 4) Move machine slowly onto trailer.
- 5) Lower the bucket onto trailer.
- 6) Put machine in the transport position or lower the bucket to the floor of the trailer.
- 7) Stop engine and set brake, put into neutral as well as place chocks at rear of each trailer.
- 8) Tie down machine with two chains using 4 point contact.
- 9) Put a cover over the exhaust pipe.
- 10) If required, ensure you have attached the wide load signs.

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards:	This Safe Work Procedure will be reviewed any	
	time the task, equipment or materials change	
MB Workplace Safety & Health Act & Regulations:	and at a minimum of every three years	
4 General Workplace Requirements	Reviewed By WSH Committee:	
6 Personal Protective Equipment		
16 Machines, Tools and Robots		
22 Powered Mobile Equipment	Date:	
. ,		