Rock Truck Operator

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Pinch points	Steel toed	Operator Certification
Slip/Trip	Eye protection	
Vehicle damage/malfunction	Hand protection	
	Hard hat	
	Safe Work Procedure:	·

- 1) Perform pre trip inspection on rock truck
- 2) Inspect work area for any potential hazards
- 3) Pull up as close as possible to loading area, if backing up use a spotter
- 4) Wait for signal that truck is full then proceed to dump area
- 5) Dump slowly and cautiously

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards:	This Safe Work Procedure will be reviewed any
MB Workplace Safety & Health Act & Regulations:	time the task, equipment or materials change
6 Personal Protective Equipment	and at a minimum of every three years
16 Machines, Tools and Robots	Reviewed By WSH Committee:
22 Powered Mobile Equipment	
	Date: